



# State of Nebraska

## Underground Storage Tank Summary Information

**Report Period: October 1, 2010 to September 30, 2011**

*This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.*

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465. Questions about Confirmed Releases may be addressed to the Department of Environmental Quality Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEQ's website at [www.deq.state.ne.us](http://www.deq.state.ne.us) under Programs/Petroleum Remediation/LUST & Surface Spill Site Information.

**Date Posted: December 1, 2011**

### **General Information**

Total Number of UST Facilities: 2530  
 Total Number of USTs: 6743

### **On Site Inspections**

# UST Facilities Inspected: 968

Percentage of Facilities Inspected Found To Be In Compliance 62%  
 (With Release Detection *and* Release Prevention Regulations)

### **Releases**

# of Confirmed UST Releases: 52

### **Leak Autopsy Report \***

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	
Tank	13	36%	0	0%	1	50%	0	0%	6	100%	0	0%	1**	100%	5	25%
Piping	6	17%	0	0%	0	0%	1	33%	0	0%	2	100%	0	0%	3	15%
Dispenser	8	22%	1	50%	0	0%	2	67%	0	0%	0	0%	0	0%	5	25%
Submersible Turbine Pump	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery Problem	1	3%	0	0%	1	50%	0	0%	0	0%	0	0%	0	0%	0	0%
Other (e.g. unknown)	8	22%	1	50%	0	0%	0	0%	0	0%	0	0%	0	0%	7	35%
Totals	<b>36</b>	100%	2	100%	2	100%	3	100%	6	100%	2	100%	1	100%	20	100%

\* NDEQ reports 52 confirmed releases. This leak autopsy report excludes 16 of the 52 for the following reasons: source unknown (5), aboveground storage tanks (6), customer dispensing overfills (3), daily inventory math error (1), and traffic accident spill (1).

\*\* The cause listed as "other" was an explosion from a lightning strike.